

RA 400 E

Brush motor

As at: 05/27/08 Time:05:23

Pos.	Description	Reference
01	Brush motor complete including Items 2-4	400.281
02	Brush motor 370W	400.281A
03	Threaded pin M 6x10 mm	P...484Y
04	Belt pulley	400.284
06	Motor holder 110x90x3 mm	400.291
07	Distribution box	400.320A
08	Cover of distribution box	P...379A
09	Wiring for motor	400.640
10	Terminal 7 poles	P...383E
11	PT-Screw KA 30x14 mm	P...516S
12	Wiring to handle	400.310S
13	Rubber clamp	P...408K
15	Hexagon socket screw M 5x16 mm	P...486I
16	Washer M5	P...496G
17	Cyl. screw M 4x20 mm	P...478L
18	Spring ring M4	P...498A
19	Hexagon nut M4	P...491Q
20	Brush complete including Items 21-23	400.470
22	Ball bearing dm 12x32 mm	P...316D
23	Centrepin dm 8x38 mm	400.478
25	Weight complete	400.350
26	Capacitor 16uF/450V	P...385C
27	Holder for capacitor	400.138
28	Screw 4.2x16	P...484Z
29	Washer M8	P...497P
30	Spring ring M8	P...498N
31	Hexagon socket screw M 8x40 mm	P...487I
32	Brush support complete including Items 33-40	400.450
33	Brush support	400.465
34	Countersunk screw M 6x60 mm	P...479T
35	Spring washer	P...498X
36	Support	400.461
37	Washer M6	P...496L
38	Stopp-nut M6	P...492K
39	Washer M5	P...497E
40	Special screw M 5x12 mm	400.475