


SW 50 Standard Vaccum motor

As at: 05/24/08 Time:08:26



SW 50 Standard Vaccum motor

As at: 05/24/08 Time:08:26

Pos.	Description	Reference
01	Isolation cap	020.211
02	Cable tree with cable clamp	020.307
03	Motorplate	020.303
04	Profile	022.133
04a	'Profile-standard	P...971H
04a	Profile-professional	P...971G
05	Vacuum motor-standard	P...870E
05	Vacuum motor-professional	P...875
06	Carbon brush up to machine No. 8449	P...874A
06	Carbon brush beg. Mach. No. 8450.001	P...875A
07	Isolation ring	020.309
08	Reinforcement piece	020.308
09	Bucket gasket	020.304
10	PT screw KA 40x16	P...516C
11	Motor cable-standard	022.143
11	Motor cable-professional up to machine No. 8449	026.143
11	Motor cable-professional beg. Mach. No. 8450.001	012.143
12	Marking plate	P...390
13	PT screw KA 30x20	P...516E
14	Airfilter for motor	022.134
15	Screw M 5x20-professional	P...488I
16	Distance piece 5.2x10x10-professional	P...509F